

## CASPIR Aircraft Accident Cards

---

**Serial:** HB109

**Title:** Beechcraft Expeditor Mk. IM / 3T serial:HB109 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1944-January-22. Beechcraft UC45B s/n HB109. This accident involved 1 person. Butterfield JE

**Keywords:** RAFBeechcraft UC45B,HB109,32 OTU,32 Operational Training Unit,Boundary Bay British Columbia,1944-January-22,ButterfieldRCAF L20

**Created:** 1944-01-22

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000565#HB109>



PURPOSE OF FLIGHT:

Circuits and landing.

TECHNICAL OFFICER'S REPORT:

Nil

NATURE OF ACCIDENT:

A/C stood on nose after landing.  
Tail wheel unlocked before speed  
sufficiently reduced; a/c swung  
off runway into very muddy area.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~61. Swinging on landing.~~

2. *Swung*

(2)

SECONDARY OR CONTRIBUTORY FACTORS:

~~32. Pilot error.~~

~~44. Bad surface.~~

~~36. Nosing up.~~

38. *Tail wheel*

(38)

ACTION TAKEN:

Nil