

CASPIR Aircraft Accident Cards

Serial: 7325

Title: Avro Anson Mk. II serial:7325 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-February-22. Anson II s/n 7325. This accident involved 1 person. Pelletier JP

Keywords: RCAFAnson II,7325,8 BGS,8 Bomb & Gunnery School,Aerodrome,1944-February-22,PelletierRCAF L20

Created: 1944-02-22

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#7325>

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Solo practice.

NIL

NATURE OF ACCIDENT:

Pilot reports that he climbed into the a/c to start the engines up and made a cockpit check prior to starting, but neglected to check his u/c lever. He started the stbd engine and then, upon starting the port engine, the u/c horn began to blow and before he could shut off the motor or check his u/c lever, the u/c retracted and the a/c went down on its belly. An examination after the accident revealed that the u/c selector had somehow been put in the up position before the pilot entered

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION: the a/c.

24. Carelessness.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Pilot logged.