

CASPIR ARCHIVAL METADATA

Serial:	10725
Title:	Fairchild Cornell Mk. II serial:10725 Accident Card
Author:	Royal Canadian Air Force (RCAF)
Subject:	This accident involved 2 aircraft on 1944-February-20. They are: Cornell II s/n 10736, Cornell II s/n 10725. This accident involved 1 person. Spencer AG
Keywords:	RCAFCornell II,10725,15 EFTS,15 Elementary Flying Training School,Aerodrome,1944-February-20,SpencerRCAF L20
Created:	1944-02-20
Link:	https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000434#10725

ACCIDENT CLASSIFICATION

UNIT	15 B.F.T.S. Regina		COM.	4	PLACE	M.A.		DATE	20-2-44	TIME	1300	
	A/C TYPE		CORNELL II CORNELL II		NO.	10736-D 10725		CRASH CAT.	"D"2 "D"		H.Q. FILE	1100-107-36
		S.E.	X		M.E.			DAY	X		NIGHT	
PERSONNEL			RANK	NUMBER	DUTY	INJURIES		SIGNAL				
SPENCER, A.G.			SGT	R66325	PP	Uninj.		NO.	DATE			
								No sig				
								D 14 (REVISED)				
								NO.	CHECKED			
								3		✓		
								#24 CR/1/1				
ENGINE		ENGINE NUMBER (S)			HOURS FLOWN BY PILOTS							
Ranger		10132/27634 6571/37054			INST.	NIGHT	ON TYPE		TOTAL			
		Nil			-	-	SOLO	DUAL	SOLO	DUAL		
							3	14	3	14		

COMMAND

MONTH

STAGE OF FLIGHT

- FORCED LANDING
- TAXIING
- LANDING
- TAKE-OFF
- FLIGHT
- STATIONARY
- FATAL
- INJ.
- 3RD
- 5

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Seq. 12,13.

TECHNICAL OFFICER'S REPORT:

NIL

TCA/FCL
TCA/YA

NATURE OF ACCIDENT:

While taxiing a/c 10736 between two lines of parked a/c, student failed when zigzagging to look out to the port side sufficiently to prevent port wing from striking stbd cowling of a/c 10725 causing slight damage to both a/c.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

24 Carelessness.

9

9. Collision

SECONDARY OR CONTRIBUTORY FACTORS:

3. Hitting other a/c.

ACTION TAKEN:

Log book endorsed.