

ACCIDENT CLASSIFICATION

UNIT # 3 S.F.T.S. Calgary, Alta.	COM. 4	PLACE M.A.	DATE 23-2-44	TIME 1025		
			H.Q. FILE 1100-79-63			
A/C TYPE CRANE I CRANE I	NO. 7872 7963 -D	CRASH CAT. "C" "D"	S.E.	M.E. X	DAY X	NIGHT

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
O'HARRA, J.M. Aus.	LAC	436808	PP	Nil	No. A7	DATE 23-2
CLAUGHTON, M.W. N.Z.	LAC	432268	PP	Nil	D 14 (REVISED)	
					No. 2	CHECKED
					# 14 2nd A/C	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
Jacobs LAMB	21259/4127 21329/4195	10	Nil	5	13	28	52
Jacobs LAMB	22631/4922 21930/4813	8	Nil	1	8	32	58

ACCIDENT CLASSIFICATION

COMMAND
 MONTH
 STAGE OF FLIGHT

FORCED LANDING
 TAXIING
 LANDING
 TAKE-OFF
 FLIGHT
 STAT BY
 FATAL
 INJ.
 3rd

TYPE OF A/C
 TYPE OF UNIT
 CATEGORY

61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31
 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61

PURPOSE OF FLIGHT:

Routine training flight.

TECHNICAL OFFICER'S REPORT:

Nil

TCA/PC

EA/PA

NATURE OF ACCIDENT:

Pupil in a/c 7963 failed to keep proper lookout when returning to hangar after landing, and in an effort to hurry across runway in use, he collided with a/c 7872 which was parked waiting for him to pass.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~24. Carelessness.~~

9. Collision

9

SECONDARY OR CONTRIBUTORY FACTORS:

~~3. Hitting other a/c.~~

ACTION TAKEN:

Awarded 10 days C.C. Pilot training suspended for 1 month.