

TYPE OF A/C		TYPE OF UNIT		CATEGORY		ACCIDENT CLASSIFICATION												TYPE OF FLIGHT													
UNIT 2 S.F.T.S. Uplands		COM. 3		PLACE R.I CAMP, Aerodrome				DATE 8-2-44		TIME 1720		H.Q. FILE 1100-31-64		COMMAND		MONTH		STAGE OF FLIGHT													
A/C TYPE HARVARD II HARVARD II				NO. 3164 2917		CRASH CAT. "D"1 "E"		S.E. X		M.E.		DAY X		NIGHT		PERSONNEL		RANK		NUMBER		DUTY		INJURIES		SIGNAL					
																THORN, G.C. 3164		LAC		E193566		P		Uninj.		NO. A.9		DATE 9-2			
																MARTIN, M.F. 2917		LAC		R211235		P		Uninj.		D 14 (REVISED)		NO. 3		CHECKED V	
								</																							

PURPOSE OF FLIGHT:

3164 Seq:5 D

2917 Seq:5

NATURE OF ACCIDENT:

LAC Thorn in Harvard 3164 taxied into stationary a/c 2917.

TECHNICAL OFFICER'S REPORT:

NIL

TOP/EST

TOP/NA

NIWT ✓

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~3. Hitting other aircraft.~~

9. Collision

9

SECONDARY OR CONTRIBUTORY FACTORS:

24. Carelessness.

ACTION TAKEN:

LAC Thorn placed on barge and his Log Book endorsed and logged for "Gross Carelessness". Awarded 168 hours

detention.
C.C.L.D. 7084.43