



PURPOSE OF FLIGHT:

Target towing.

TECHNICAL OFFICER'S REPORT:

Carb. icing. OFM/ADP/52/PTM/WIE

NATURE OF ACCIDENT:

Pilot reports that on take-off, when at 50', the engine failed and he landed the a/c straight ahead but could not stop the a/c rolling forward until it had gone through the fence at end of runway in use. When a/c went through the fence, the stabalizer caught the fence post damaging same.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~13. Engine failure.~~

15 Forced Land.

SECONDARY OR CONTRIBUTORY FACTORS:

~~1. Hitting obstructions.~~

ACTION TAKEN:

NIL