


ACCIDENT CLASSIFICATION

UNIT 1 C.A.C. St. John		COM. "E"	PLACE Pogwa Lake			DATE 2-2-44	TIME 1725		
A/C TYPE LYSANDER II		No. 455	CRASH CAT. F 		S.E. X	M.E.	DAY X	NIGHT	
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL		
HODDER, J.		F/O	C22313	P	Uninj.		No.	DATE	
PRITCHARD, J.J.		CPL	R97189	CM	Uninj.		A.140	23-2	
							D 14 (REVISED)		
							No.	CHECKED	
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS					
				ON TYPE		TOTAL			
				INST.	NIGHT	SOLO	DUAL	SOLO	DUAL

ACCIDENT CLASSIFICATION

COMMAND  
MONTH  
STAGE OF FLIGHT

FORCED LANDING  
TAXYING  
LANDING  
TAKE-OFF  
FLIGHT  
STAT BR  
FATAL  
INI.  
3rd  
INJURY

61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

TYPE OF A/C  
TYPE OF UNIT  
CATEGORY

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

REF M 2 5

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

En route to unit on completion of  
I.A.D. photography detail Halifax area.

*Copy of Flight Report*

NATURE OF ACCIDENT:

Left St John on a photographic mission

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

The engine of the plane caught fire  
when over St. Margarets Bay area and  
they immediately landed on a lake  
surface nearby. Landed on lake O.K.  
and located by plane sent out by  
E.A.C.

FINDINGS:

SUMMARY No.

CLASSIFICATION:

54. Engine failure in the air.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN: