

CASPIR Aircraft Accident Cards

Serial: R9633

Title: Avro Anson Mk. I serial:R9633 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-March-10. Anson I s/n R9633. This accident involved 5 people. Bryand RW, Butts EO, Grimsrud HA, Mcinnes DA, Mitchell A

Keywords: RCAFAnson I,R9633,5 AOS,5 Air Observer School,Brandon Manitoba,1944-March-10,Bryand,Butts,Grimsrud,Mcinnes,MitchellRCAF L20

Created: 1944-03-10

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#R9633>

PURPOSE OF FLIGHT:

Navigation and air bomber training.

TECHNICAL OFFICER'S REPORT:

Intake valve seat #2 cylinder Port engine, became loose and dropped out.

NATURE OF ACCIDENT:

When mixture put into "rich" position at start of climb, port engines began to backfire. Temperature and pressure appeared satisfactory but could not remedy trouble, so cut switches on port engine, and flew single engine to Brandon airport.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

54. Engine failure in the air.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL