

## CASPIR Aircraft Accident Cards

---

**Serial:** FE913

**Title:** North American Harvard Mk. IIB serial:FE913 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 2 aircraft on 1944-March-13. They are: Harvard II s/n 2509, Harvard IIB s/n FE913. This accident involved 3 people. Burns D, Dorward AP, Martin EC

**Keywords:** RAFHarvard IIB,FE913,34 SFTS,34 Service Flying Training School,Aerodrome,1944-March-13,Burns,Dorward,MartinRCAF L20

**Created:** 1944-03-13

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE913>

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S. Medicine Hat	COM. 4	PLACE M.A.	DATE 13-3-44	TIME 0900
A/C TYPE HARVARD II HARV. RD IIB	NO. 2509 D FE913	CRASH CAT. "E"1 "D"3	S.E. X	M.E. DAY X
		H.Q. FILE 1100-25-09		NIGHT

TYPE OF A/C

TYPE OF UNIT

CATEGORY

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
DORWARD, A.F.	F/O	152890	FI	Uninj.	NO.	DATE
MARTIN, E.C.	LAC	1583521	PP	Uninj.	A.628	13-3
BURNS, D.	LAC	1600137	PP	Uninj.	D 14 (REVISED)	
					NO.	CHECKED
					6	<input checked="" type="checkbox"/>
					#22 759	

COMMAND

MONTH

STAGE OF FLIGHT

4  
2  
1  
7  
4  
2  
1  
FORCED LANDING  
TAXYING  
LANDING  
TAKE-OFF  
FLIGHT  
STATRY  
FATAL  
INJ.  
INJURY  
3RD  
5  
N

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
Wasp S3HI	213650/11369 Nil	-	-	462	107	499	160
	429491/21830 Nil	-	-	36	99	60	111
				68	83	208	125

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

(i) Formation flying.

(ii) Solo exercise.

NIL

NATURE OF ACCIDENT:

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

Pilot of a/c 2509 taxied into stationary a/c FE913.

FINDINGS:

SUMMARY No.

*MULT  
75A/100 ✓  
75A/1A*

CLASSIFICATION:

3. Hitting other a/c.

9

SECONDARY OR CONTRIBUTORY FACTORS:

24. Carelessness.

ACTION TAKEN:

Log book endorsed "Gross Carelessness".