

## CASPIR Aircraft Accident Cards

---

**Serial:** 2769

**Title:** North American Harvard Mk.II serial:2769 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1944-March-15. Harvard II s/n 2769. This accident involved 1 person. Baker FH

**Keywords:** RAFHarvard II,2769,34 SFTS,34 Service Flying Training School,Whitla R2,1944-March-15,BakerRCAF L20

**Created:** 1944-03-15

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2769>



PURPOSE OF FLIGHT:

Solo exercises.

TECHNICAL OFFICER'S REPORT:

Nil

NATURE OF ACCIDENT:

Forced landing with u/c retracted. Carrying out spinning, pilot came out of spin at 8000' and found the throttle stuck. He then forced landed. No indication of carb. icing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

FB/AOM/ET/PM/M/I/UCK/B ✓

CLASSIFICATION:

17

47. Weather.

SECONDARY OR CONTRIBUTORY FACTORS:

34. Wheels up landing.

26

ACTION TAKEN:

Nil.