

## CASPIR Aircraft Accident Cards

---

**Serial:** FE309

**Title:** North American Harvard Mk. IIB serial:FE309 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1944-March-18. Harvard IIB s/n FE309. This accident involved 1 person. Saunders TC

**Keywords:** RAFHarvard IIB,FE309,34 SFTS,34 Service Flying Training School,Aerodrome,1944-March-18,SaundersRCAF L20

**Created:** 1944-03-18

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE309>

61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

UNIT <b>34 S.F.T.S. Medicine Hat</b>	COM. <b>4</b>	PLACE <b>M.A.</b>	DATE <b>18-3-44</b>	TIME <b>1840</b>
A/C TYPE <b>HARVARD IIB</b>		NO. <b>FE309</b>	CRASH CAT. <b>"E"<sup>1</sup>/<sub>4</sub></b>	H.Q. FILE <b>1300-FE309</b>
		S.E. <b>X</b>	M.E.	DAY <b>X</b>
				NIGHT

COMMAND

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL
<b>SAUNDERS, T.C.</b>	<b>F/O</b>	<b>J15688</b>	<b>PP</b>	<b>Uninj.</b>	NO. DATE <b>No sig</b>
					D 14 (REVISED) NO. CHECKED <b>11</b> ✓
					<b>#48</b>

MONTH

STAGE OF FLIGHT

ENGINE <b>Wasp R1340ANI</b>	ENGINE NUMBER (S) <b>42705/15841 Nil</b>	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
		<b>-</b>	<b>-</b>	<b>40</b>	<b>66</b>	<b>161</b>	<b>106</b>

FORCED LANDING  
TAXING  
LANDING  
TAKE-OFF  
FLIGHT  
STATALY  
FATAL  
INJ. 3RD  
INJURY

TYPE OF A/C  
TYPE OF UNIT  
CATEGORY

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 RAF M N

PURPOSE OF FLIGHT:

Solo exercises.

TECHNICAL OFFICER'S REPORT:

NATURE OF ACCIDENT:

NIL

Pilot while taxiing, failed to notice a post when swinging the tail round, struck the post,

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

2. Hitting obstructions.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Log book endorsed "Carelessness".