

61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S. Medicine Hat	COM. 4	PLACE M.A.	DATE 18-3-44	TIME 1840
A/C TYPE HARVARD IIB		NO. FE309	CRASH CAT. "E" 1/4	H.Q. FILE 1300-FE309
		S.E. X	M.E.	DAY X
				NIGHT

COMMAND

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL
SAUNDERS, T.C.	F/O	J15688	PP	Uninj.	NO. DATE No sig
					D 14 (REVISED) NO. CHECKED 11 <input checked="" type="checkbox"/>
					#48

MONTH

STAGE OF FLIGHT

ENGINE Wasp R1340ANI	ENGINE NUMBER (S) 42705/15841 Nil	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
		-	-	40	66	161	106

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ. 3RD
INJURY

TYPE OF A/C
TYPE OF UNIT
CATEGORY

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 RAF M N

PURPOSE OF FLIGHT:

Solo exercises.

TECHNICAL OFFICER'S REPORT:

NATURE OF ACCIDENT:

NIL

Pilot while taxiing, failed to notice a post when swinging the tail round, struck the post,

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

2. Hitting obstructions.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Log book endorsed "Carelessness".