

CASPIR Aircraft Accident Cards

Serial: 3274

Title: North American Harvard Mk.IIB serial:3274 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1944-March-27. Harvard II s/n 3274. This accident involved 1 person. Wallwork JT

Keywords: RAFHarvard II,3274,34 SFTS,34 Service Flying Training School,R1 Holsom,1944-March-27,WallworkRCAF L20

Created: 1944-03-27

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#3274>

PURPOSE OF FLIGHT:

L.L.B. & L.D.B. Exercises.

TECHNICAL OFFICER'S REPORT:

Nil

05/PSS/WWC ✓

NATURE OF ACCIDENT:

Ground loop on take off.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

Remarks of Unit C.O.

Runway slightly out-of-wind.

CLASSIFICATION:

9. Swinging.

12

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil.