

81 () 60 () 59 () 58 () 57 () 56 () 55 () 54 () 53 () 52 () 51 () 50 () 49 () 48 () 47 () 46 () 45 () 44 () 43 () 42 () 41 () 40 () 39 () 38 () 37 () 36 () 35 () 34 () 33 () 32 () 31 ()

ACCIDENT CLASSIFICATION

UNIT # 1 F.I.S. Trenton, Ont	COM. 1	PLACE M.A.	DATE 30-3-44	TIME 1140
A/C TYPE CRAIB IA HARVARD IIB	NO. FJ233-D FE576	CRASH CAT. "D6" "E ₂ "	H.Q. FILE 1300-FJ233	S.E. x M.E. x DAY x NIGHT

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Atkinson, F.	F/O	C28048	FI	Nil	NO.	DATE
Daw, C.B.	P/O	R186433	PP	Nil	A478	30-3

D 14 (REVISED)		
NO.	CHECKED	
# 21		

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS				TOTAL	
		INST.	NIGHT	ON TYPE		SOLO	DUAL
				SOLO	DUAL		
Jacobs	4786/21811 Nil			21807			
	13656/36431 Nil						
Wasp	42-1586/21510 Nil	72	128	42	13	1937	150
		36	24	Nil	2	94	125
						219	

ACCIDENT CLASSIFICATION

1 () 2 () 3 () 4 () 5 () 6 () 7 () 8 () 9 () 10 () 11 () 12 () 13 () 14 () 15 () 16 () 17 () 18 () 19 () 20 () 21 () 22 () 23 () 24 () 25 () 26 () 27 () 28 () 29 () 30 () 31 ()

TYPE OF A/C
TYPE OF UNIT
CATEGORY

COMMAND
MONTH
STAGE OF FLIGHT
FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJURY
3rd
5
4
3
2
1
7
1
2
4
1
2
4
7

PURPOSE OF FLIGHT:

Routing flying instruction.

TECHNICAL OFFICER'S REPORT:

Nil

NATURE OF ACCIDENT:

Taxiing. Crane FJ233 taxied into Harvard FE576 which was parked on edge of tarmac.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

MULT
TCR/PC1
MA/AA ✓

CLASSIFICATION:

3. Hitting other aircraft.

9

SECONDARY OR CONTRIBUTORY FACTORS:

24. Carelessness.

ACTION TAKEN:

Pilot's log book endorsed.