

## CASPIR Aircraft Accident Cards

---

**Serial:** 8265

**Title:** Avro Anson Mk. II serial:8265 Accident Card

**Author:** Royal Canadian Air Force (RCAF)

**Subject:** This accident involved 1 aircraft on 1944-April-20. Anson II s/n 8265. This accident involved 1 person. Andrew CL

**Keywords:** RCAFAnson II,8265,170 Sqn,170 Ferry Squadron,Municipal Airport,1944-April-20,AndrewRCAF L20

**Created:** 1944-04-20

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#8265>



PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT: LUC/PODUF/UCDL

Ferrying.

NIL

NATURE OF ACCIDENT:

Wheels up landing. On downwind approach COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

ch pilot throttled back slightly to FINDINGS:

SUMMARY No.

lose extra height and the u/c warning horn commenced blowing. Pushed the cut-out and proceeded with circuit. Pilot checked switches, fuel and mixture controls and closed the throttles. Horn did not blow due likely to the fact that pilot had not opened up throttles sufficiently to re-set horn on a/c. Pilot did not check mechanical warning devices. Completed cross-wind leg and commenced

CLASSIFICATION: final approach, lowering flaps preparatory to landing.

~~34. Wheels up landing.~~

~~7~~ *Other*  
SECONDARY OR CONTRIBUTORY FACTORS:

~~38. Pilot error.~~

ACTION TAKEN:

~~32~~ *left Dull - in air*  
~~24. Carelessness.~~

Log book endorsed.