

## CASPIR Aircraft Accident Cards

---

**Serial:** FP786

**Title:** Avro Anson Mk. II serial:FP786 Accident Card

**Author:** Royal Canadian Air Force (RCAF)

**Subject:** This accident involved 1 aircraft on 1944-April-21. Anson II s/n FP786. This accident involved 2 people. Bergiron JMT, Blackford CL

**Keywords:** RCAFAnson II,FP786,17 SFTS,17 Service Flying Training School,Aerodrome,1944-April-21,Bergiron,BlackfordRCAF L20

**Created:** 1944-04-21

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#FP786>



PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT: *400/0 DM*

Maintenance test flight.

NATURE OF ACCIDENT:

Port u/c would not lock in the down position. After several attempts to lock the u/c the pilot decided to attempt a landing. After landing, the a/c ran for considerable distance along the runway, and then port u/c collapsed.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~33. Technical defect.~~

*18* *Tric. Technical*

SECONDARY OR CONTRIBUTORY FACTORS:

*35* *w/b defect*

ACTION TAKEN:

*Nil*