

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62

ACCIDENT CLASSIFICATION

UNIT	13 S.F.T.S. North Battleford	COM.	4	PLACE	4 mles E of Maidstone	DATE	26-4-44	TIME	1045
A/C TYPE	ANSON II			NO.	7411	CRASH CAT.	"B"		
		S.E.		M.E.	X	DAY	X	NIGHT	
H.Q. FILE	1100-74-11								

COMMAND

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
WARRINER, G.E.	P/O	J29814	SP	Uninj.	NO.	DATE
MCLEAN, O.G.	F/L	C6913	NAV	Uninj.	AC18	27-4
WHEELER, R. AUS	LAC	436577	PP	Uninj.	D 14 (REVISED)	
HEYNS, J.W. AUS	LAC	432987	P	Uninj.	NO.	CHECKED
					16	
					#52	

MONTH

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		NIGHT	ON TYPE		TOTAL		
Jacobs	26669/9923 port engine	85	190	SOLO	DUAL	SOLO	DUAL
	19790/25902 slightly			240	2	1874	177

STAGE OF FLIGHT

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52

4
2
1
7
4
2
1
1
FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ
3RD
INJURY
S
M 2

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT: *11/11/68/006/13*

Nao. ex 5.

NATURE OF ACCIDENT:

NIL

Port engine failed - vibration and
smoke evident - force landed in
field - wheels up.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~34. Wheels up landing.~~

17 *Forced Landing*

SECONDARY OR CONTRIBUTORY FACTORS:

~~54. Engine failure in the air.~~

ACTION TAKEN:

26 *Engine Trouble - Accident* NIL