

ACCIDENT CLASSIFICATION

UNIT **3 B.G.S.** COM. **2** PLACE **NE side of #2 Runway at M.A.** DATE **6-4-44** TIME **1235**  
**MacDonald** A/C FILE **1100-101-44**

A/C TYPE **BOLINGBROKE IVT** NO. **10144** CRASH CAT. **"A"** S.E. **X** M.E. **X** DAY **X** NIGHT

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
BRINKMAN, O. AUS	F/S	421155	P	Uninj.	NO.	DATE
MCDONALD, C.H.	LAC	R268101	AG	Uninj.	N10	6-5
MCIVER, J.S.	LAC	R277987	AG	Uninj.	D 14 (REVISED)	
MCKELLER, R.G.	LAC	R204728	AG	Uninj.	NO.	CHECKED
					2	<input checked="" type="checkbox"/>
					#7	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
Mercury XX	12050/56753	45	2	22	3	610	268
	11976/57328						

ACCIDENT CLASSIFICATION

COMMAND  
MONTH  
STAGE OF FLIGHT

FORCED LANDING  
TAXIING  
LANDING  
TAKE-OFF  
FLIGHT  
STATRY  
FATAL  
INJ.  
INJURY 3RD  
INJURY 5TH

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62

PURPOSE OF FLIGHT:

Gunnery exercise.

TECHNICAL OFFICER'S REPORT:

*0 FM/AGP/EE/NA/10*

NIL

NATURE OF ACCIDENT:

Stbd engine failed on take-off.  
Pilot forced landing on aerodrome.

*CAUSE OF E/F obscure*

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~14. Engine failure in the air.~~

*17 Forced Landing*

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

*26 Engine Trouble - Accident*

NIL