

CASPIR Aircraft Accident Cards

Serial: FE929

Title: North American Harvard Mk. IIB serial:FE929 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1944-April-11. Harvard IIB s/n FE929. This accident involved 1 person. Fyfe DJ

Keywords: RAFHarvard IIB,FE929,34 SFTS,34 Service Flying Training School,Aerodrome,1944-April-11,FyfeRCAF L20

Created: 1944-04-11

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE929>

PURPOSE OF FLIGHT:

Solo exercise.

TECHNICAL OFFICER'S REPORT:

1. 1/2/61 ✓

NIL

NATURE OF ACCIDENT:

Pupil pilot landing, overshoot slightly, and on applying brake the a/c swung causing port wing to touch ground.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~29. Overshooting runway.~~

1. Overshoot!

SECONDARY OR CONTRIBUTORY FACTORS:

~~61. Swinging on runway.~~

~~25. Inexperience.~~

ACTION TAKEN:

NIL