

## CASPIR Aircraft Accident Cards

---

**Serial:** AJ798

**Title:** North American Harvard Mk. II / 2 serial:AJ798 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1944-April-17. Harvard II s/n AJ798. This accident involved 2 people. Hammond JSR, Mortimer AM

**Keywords:** RAFHarvard II,AJ798,34 SFTS,34 Service Flying Training School,Aerodrome,1944-April-17,Hammond,MortimerRCAF L20

**Created:** 1944-04-17

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ798>



PURPOSE OF FLIGHT:

Aerobatics.

TECHNICAL OFFICER'S REPORT:

Failure of master rod bearing.

NATURE OF ACCIDENT:

Engine stopped while gliding after doing aerobatics. Pilot was unable to restart it and carried out a successful forced landing on the aerodrome.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

54. Engine failure in the air.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL