

ACCIDENT CLASSIFICATION

UNIT	34 S.F.T.S. Medicine Hat		COM.	4	PLACE	M.A.		DATE	22-4-44	TIME	1815	
	A/C TYPE		HARVARD II		No.	AJ737		H.Q. FILE	1300-AJ737			
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL					
DENEYER, E.J.J.G.		LAC	1814831	PP	Uninj.		No.	DATE				
							D 14 (REVISED)					
							No.	CHECKED				
							#4					
							#96					
ENGINE	ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS									
	Was: S3HI	4041/7823 Nil		INST.	NIGHT	ON TYPE		TOTAL				
				-	11	SOLO	DUAL	SOLO	DUAL			
						20	46	57	94			

COMMAND

MONTH

STAGE OF FLIGHT

4
2
1
7
4
2
1
FORCED LANDING
TAXYING
LANDING
TAKEOFF
FLIGHT
STATRY
FATAL
INJ.
3RD
INJURY
S

ACCIDENT CLASSIFICATION

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	RAF	M
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----	---

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62

TYPE OF A/C

TYPE OF UNIT

CATEGORY

PURPOSE OF FLIGHT:

Solo cross country.

TECHNICAL OFFICER'S REPORT:

LS/MS ✓

NIL

NATURE OF ACCIDENT:

Ground loop on landing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~61. Swinging on landing.~~

2. *Swing*

SECONDARY OR CONTRIBUTORY FACTORS:

~~38. Ground loop.~~

ACTION TAKEN:

NIL