

ACCIDENT CLASSIFICATION									
UNIT No. 11 Sqdm. Torbay, Nfld.		COM. EAC	PLACE TORBAY		DATE 25-4-44	TIME 1145		H.Q. FILE	
A/C TYPE HEMDSON III		NO. 712		CRASH CAT. "B"	S.E.	M.E. X	DAY X	NIGHT	
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL		
Cook, G.M.		W/C	C1059	P	Uninj.		No.		DATE
Snyder, W.S.		F/L	J25558	NAV	Uninj.				
O'Sullivan, H.P.		P/O	J41969	WAG	Uninj.		D 14 (REVISED)		
Luscott, W.C.		LAC		Pass	Uninj.		No.		CHECKED
Dr. E.C. Smith		ORS		Pass	Uninj.				
Dr. J.H. Soper		ORS		Pass	Uninj.				
							#4		
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS					
Wright Cyclone A211278/		S.39486		INST.	NIGHT	ON TYPE		TOTAL	
		P.39562				SOLO	DUAL	SOLO	DUAL
				92	193	329	6	2014	98
ACCIDENT CLASSIFICATION									

PURPOSE OF FLIGHT:

Demonstration of Rocket Weapon

NATURE OF ACCIDENT:

Throttle stuck part way open on
landing resulting in ground loop at
end of landing run.

TECHNICAL OFFICER'S REPORT: LG/AMM

Small piece of Flexiglass became jammed under throttle

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

33. Technical defect. (2)

2. Swung

SECONDARY OR CONTRIBUTORY FACTORS:

38. Ground loop.

ACTION TAKEN:

NIL