

TECHNICAL OFFICER'S REPORT: PURPOSE OF FLIGHT: Navigation and camera obscura training flicht. NATURE OF ACCIDENT: COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: A/C airborne at 0030 hrs. GMT. During SUMMARY No. 2362 FINDINGS: flight a very high S.W. wind arose. A/C became lost due to deteriorating All a/c on this frequency were reweather conditions and were unable to locate) called at 0215 hrs. GMT.:11600 was rebase. (a) Lack of proper flying Operations) called individually at 0225 and immediateorganization. (b) Inferior and obsolete wirely acknowledged. At 0257 hrs. GMT. the a/c less equipment. asked and was granted permission to change RECOMMENDATIONS See Summary 2362 to radio range frequency. Although called several times by ground station. all contact REMARKS OF A.O.C. Note: See copy of letter with m/c was lost. attached hereto. CONCLUSIONS OF A.I.B. Agree with findings.) CLASSIFICATION: It is doubtful whether the exercise should have been authorized at all in view of the weather information available. SECONDARY OR CONTRIBUTORY FACTORS: **ACTION TAKEN:** 111 R. C. A. F. L 20 (REVISED) 7M.4.43 (3202) K.P. 5051 C. C. LTD, 7084-43 H. O. 885-L 20