

TECHNICAL OFFICER'S REPORT: PURPOSE OF FLIGHT: OOC AOC! PUDM ) Routine navigation. NATURE OF ACCIDENT: A/C crashed just after take-off. -COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: stbd wing hit ground causing a/c to SCAMMARY No. 2353 FINDINGS: CAUSE: Gross carelessness on part of pilot in that he cartwheel to right - badly damaging same, and injuring all members of the failed to make a regular cockpit check before take offas a result of which he took off with aileron crew. controls locked to the control column by a strap. a/c having no lateral control banked to stbd. and crashed. RECOMMENDATIONS: Disciplinary action would be recomm.) ended against the pilot if he were under service jurisdiction. Chief Coroner of Province of Manitoba is holding an inquest and advised the Investigating CLASSIFICATION: officer that criminal proceedings in civil court would probably be taken against pilot. Oversurning. CONCLUSIONS OF A.I.B.: Agree with findings. Loss of control after take off due to pilot's gross SECONDARY OR CONTRIBUTORY FACTORS: carelessness. NOTE 1: Evidence indicated that ambul-ACTION TAKEN: ance was slow in arriving at crash. Caralasanana-Log book endorsed Gross Carelessness" R. C. A. F. L 20 (REVISED) C. C. LTD. 7084-43 H. Q. 885.L 20