

PURPOSE OF FLIGHT:

Target a/c. for camera-gun exercise.

NATURE OF ACCIDENT:

N.A. Ground loop.

TECHNICAL OFFICER'S REPORT:

LUC / JTWI ✓
Structural failure tail-wheel unit.
SHEAR PIN SHERED ALLOWING TAIL WHEEL
TO ROTATE *could not be controlled by Rudder
pedals.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~33. Technical defect.~~

5 1/6 Tailwire 5

SECONDARY OR CONTRIBUTORY FACTORS:

~~61. Swinging on landing.~~

38 Tailwheel 38

ACTION TAKEN:

NIL.