

62 61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

UNIT 8 Sqn	COM. W	PLACE Patricia Bay, B.C.	DATE 23-5-44	TIME 1145
A/C TYPE VENTURA G.R.V.	No. 2175	CRASH CAT. "C"	H.Q. FILE 1100-21-75	
			S.E.	M.E. X
			DAY	NIGHT

COMMAND

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
HANCHET, W.H.D.	F/O	J9455	P	Uninj.	No.	DATE
MCQUAID, C.L.	F/O	J40460	OBS	Uninj.	A874	24-5
MCDONALD, I.E.	WOI	R92135	WO	Uninj.	D 14 (REVISED)	
BACKING, J.E.T.	F/S	R105709	WO	Uninj.	No. 1	CHECKED
					#2	

MONTH

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
FLIGHT
FATAL
INJ.
3RD
5

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
		45	30	SOLO 125	DUAL 10	SOLO 525	DUAL 75

STAGE OF FLIGHT

TYPE OF A/C
TYPE OF UNIT
CATEGORY

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 RAF W M

PURPOSE OF FLIGHT:

Search for missing a/c.

NATURE OF ACCIDENT:

While turning on reve tment
tail wheel struck off on to rough
ground and was wrenched from tail
section.

TECHNICAL OFFICER'S REPORT:

TBG/PCT/USG
NIL TBG/PCT/USG

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

2. ~~Hitting obstructions.~~

9 collisions

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Pilot placed on charge for negligence.