

ACCIDENT CLASSIFICATION										
UNIT 33 SFTS	COM. 2	PLACE Deerwood	DATE 1-6-44	TIME 1432	H.Q. FILE 1100-84-45	S.E.	M.E.	DAY	NIGHT	COMMAND MONTH STAGE OF FLIGHT
A/C TYPE Andon Mk II	No. 8845	CRASH CAT. "D"	X	X						
PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	No.	DATE			
STANSFIELD, H.L.	P/O	154136	P/NAV	Nil		A43	2-6-44			
TUCK, C.N.	LAC	1625653	PP	Nil		#2	CHECKED			
XXXXXXXXXX										
ENGINE	ENGINE NUMBER(S)		HOURS FLOWN BY PILOTS							
L6MB Jacobs	10657/25933 10463/25759		INST.	NIGHT	ON TYPE		TOTAL			
					SOLO	DUAL	SOLO	DUAL		
			38	41	201	94	223	166		
			16	5	16	31	54	81		
ACCIDENT CLASSIFICATION										

PURPOSE OF FLIGHT:

Low Level Cross Country,

TECHNICAL OFFICER'S REPORT:

Nil

1400/20 M

NATURE OF ACCIDENT:

Aircraft struck tree while on an
authorized low level cross country
flight.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~174--Disobedience-of-standing-orders.~~

41. Disobedience of Orders.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN: