

TECHNICAL OFFICER'S REPORT: PURPOSE OF FLIGHT: A/C being flown out of field after forced landing. NATURE OF ACCIDENT: COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: Pilot taking off from field after FINDINGS: SUMMARY No. a forced landing, struck fence CAUSE: Post which caused accident was below level of post, tearing off port stabilizer take off path and was not observed or considered by and elevator. Unable to maintain pilot before take off. control, crasho landed after 20 CIRCUMSTANCES: A/C str ck post with tailplane on tak minutes flight. ing off rendering it uncon rolable. NOTE: Pilots should be instructed that before taking off a forced-landed a/c, to personally walk over entire take-off path to sensure that the length of run is sufficient and satisfactory, and that any CLASSIFICATION: obstacles at the windward end of the field, such as posts fences, etc., are duly noted, or if necessary **万月月**曜年間到在電電車祭を三名を伝統を同心を示いれた。 removed entirely prior to take-off, Arrangements car, Collisions. always be made to have such obstacles replaced after the take-off, and any expense involved is well jus-SECONDARY OR CONTRIBUTORY FACTORS: tified. **ACTION TAKEN:** NIL R. C. A. F. L 20 (REVISED) 7M-4-43 (3202) K. P. 5051 H. C. 885.L 20 C. C. LTD. 7084-43