

CASPIR Aircraft Accident Cards

Serial: FP767

Title: Avro Anson Mk. II serial:FP767 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1944-June-06. Anson II s/n FP767. This accident involved 2 people. Pettitt ET, Quick JN

Keywords: RAFAnson II,FP767,33 SFTS,33 Service Flying Training School,8 RC
Winnipeg,1944-June-06,Pettitt,QuickRCAF L20

Created: 1944-06-06

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#FP767>

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Routine cross country navigation exercise. Drive of port engine fuel pump sheared causing leakage of fuel into crankcase and excessive dilution of oil. On e piston partially seized.

NATURE OF ACCIDENT:

Pilot landed with engine trouble, at 8 R.D. who attempted to engine which however, failed soon after take-off. Pilot made safe single engine landing on Winnipeg aerodrome.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

340/2/10/12

CLASSIFICATION:

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL