



PURPOSE OF FLIGHT:

Navigation exercise.

NATURE OF ACCIDENT:

Pilot landed at nearest aerodrome following engine failure.

TECHNICAL OFFICER'S REPORT:

Inspection revealed broken exhaust rocker arm. No. 2 cylinder.

*SPE/ET/VA/0/11*

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~54. Engine failure in the air.~~

27. Engine Trouble - No Damage.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL