

CASPIR Aircraft Accident Cards

Serial: FP853

Title: Avro Anson Mk. II serial:FP853 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-June-12. Anson II s/n FP853. This accident involved 3 people. Doctoroff SH, Fanson JH, Goulding AG

Keywords: RCAFAnson II,FP853,18 ,18 Service Flying Training School
GIMILI,Aerodrome,1944-June-12,Doctoroff,Fanson,GouldingRCAF L20

Created: 1944-06-12

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#FP853>

182 81 80 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31 7 4 2 1

ACCIDENT CLASSIFICATION

UNIT 18 SFTS Gimili	COM. 2	PLACE 1 1/2 miles east 1/2 mile west of M.A.	DATE 12-6-44	TIME 1350
A/C TYPE ANSON 11		NO. FP853	CRASH CAT. D.1	H.Q. FILE 1300-FP853
		S.E.	M.E.	DAY
			X	X
		NIGHT		

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
GOULDING, A.G.	W/C	C1980	P	Nil	NO.	DATE
FANSON J.H.	F/L	J8650	2P	Nil	A.43	12-6
DOCTOROFF S.H.	F/O	C12412	Na v	Nil	D 14 (REVISED)	
					NO.	CHECKED
					3	
					#5	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
SOLO	DUAL			SOLO	DUAL		
Jacobs	P1 5911	2096					
L6MB	S25840	10544					
			03:00	03:00	06:00	89	6 94
			63	128	216	38	1351 143

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 RAF M 4

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJURY 3RD
INJURY 5

PURPOSE OF FLIGHT:

X Country from Gimli to Dauphin.

NATURE OF ACCIDENT:

While climbing after take-off
Stbd engine ceased firing. Normal
S.E. action was instituted and
immediately after, port engine ceased
firing. A/C was forced landed,
wheels retracted. All engine instruments
appeared to function normally.

TECHNICAL OFFICER'S REPORT:

Water found in port and stbd engine fuel filters
and in stbd outer gas tanks.

OFM/AOP/ES/PM/GC/0014/B/XFM

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

Remarks of Unit C.O.

All unit A/C grounded pending inspection
for water in gas tanks.

CLASSIFICATION:

17. Forced landing.

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine trouble- accident.

ACTION TAKEN:

Nil.