

ACCIDENT CLASSIFICATION

UNIT 10 S.F.T.S. COM. 2 PLACE M.A. DATE 30-6-44 TIME 0920
 Dauphin 2

A/C TYPE CRANE No. 8102 D CRASH CAT. "D"7
 CRANE 7828 "D"2 S.E. M.E. DAY NIGHT
 X X X

| PERSONNEL | RANK | NUMBER | DUTY | INJURIES | SIGNAL | |
|---------------|------|---------|------|----------|----------------|---------|
| HOUSTON, G.S. | P/O | J37592 | FI | Uninj. | No. | DATE |
| TURNER, C.C. | LAC | R266187 | PP | Uninj. | A92 | 30-6 |
| ELLIOTT, B.J. | P/O | J39560 | FI | Uninj. | D 14 (REVISED) | |
| SANES, D.A. | LAC | R257297 | PP | Uninj. | No. | CHECKED |
| | | | | | | X |
| | | | | | #13 | |


| ENGINE | ENGINE NUMBER (S) | HOURS FLOWN BY PILOTS | | | | | |
|-------------|-------------------|-----------------------|-------|---------|------|-------|------|
| | | INST. | NIGHT | ON TYPE | | TOTAL | |
| | | | | SOLO | DUAL | SOLO | DUAL |
| Jacobs L4ME | 42791/21480 N11 | | | | | | |
| | 4136/21278 N11 | | | | | | |
| | 4441/21609 N11 | 68 | 52 | 126 | 96 | 352 | 194 |
| | 4602/22509 N11 | 24 | 10 | 28 | 42 | 64 | 86 |
| | | 57 | 46 | 185 | 144 | 227 | 193 |
| | | 22 | 10 | 27 | 38 | 66 | 78 |

ACCIDENT CLASSIFICATION

TYPE OF A/C
TYPE OF UNIT
CATEGORY

COMMAND
MONTH
STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STAT'RY
FATAL
INJ.
3RD
INJURY



PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

8102 - General seq.

7828 - Instrument flying.

NATURE OF ACCIDENT:

NIL

MULT
510/TCA/PCT/II
250/TCA/XT
MULT
TCA/PCT/II
TCA/XA

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

Pilot of a/c 8102 working radio for take-off clearance, student taxied stbd wing into port prop of Grane 7828 which was parked at edge of runway running up engines.

CLASSIFICATION:

9 Collisions.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN: