

CASPIR Aircraft Accident Cards

Serial: 11525

Title: Avro Anson Mk. II serial:11525 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-July-04. Anson II s/n 11525. This accident involved 1 person. Shaw H

Keywords: RCAFAnson II,11525,19 SFTS,19 Service Flying Training School,Aerodrome,1944-July-04,ShawRCAF L20

Created: 1944-07-04

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#11525>

ACCIDENT CLASSIFICATION

UNIT 19 S.F.T.S. Vulcan, Alta.	COM. A	PLACE M.A.	DATE 4-7-44	TIME 2345
A/C TYPE ANSON II	No. 11525	CRASH CAT. WC	H.Q. FILE 1100-115-25	
		S.E.	M.E.	DAY NIGHT X X

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL
Shaw, H.	GB CPL	972732	PP	Uninj.	No. A113 DATE 5-7-44
					D 14 (REVISED)
					No. CHECKED <input checked="" type="checkbox"/>
					#6

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				DUAL	SOLO	DUAL	SOLO
Jacobs LOMB	P.17981/93 54 Slight 8.15395/25706 Nil	24	7	46	31	88	79

ACCIDENT CLASSIFICATION

COMMAND

MONTH

STAGE OF FLIGHT

- FORCED LANDING
- TAXIING
- LANDING
- TAKE-OFF
- FLIGHT
- STATRY
- FATAL
- INJ.
- INJURY
- SRP
- S
- RAF
- W

TYPE OF A/C

TYPE OF UNIT

CATEGORY

PURPOSE OF FLIGHT:

Training - Night Flying Circuits.

TECHNICAL OFFICER'S REPORT:

Nil.

LO/PSO/XCA

LO/PSO

NATURE OF ACCIDENT:

Pupil landed near the approach end of runway, but due to slight down-wind conditions, ran off end of runway and struck a large drainage ditch which is situated about 100 yds. off end of runway.

FINDINGS:

SUMMARY No.

CLASSIFICATION:

1. Overshot.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil.