

ACCIDENT CLASSIFICATION

UNIT <b>33 S.F.T.S. Carberry, Man.</b>	COM. <b>2</b>	PLACE <b>M.A.</b>	DATE <b>10-7-44</b>	TIME <b>1645</b>
A/C TYPE <b>ANSON II ANSON II</b>	NO. <b>8439 - D 8454</b>	CRASH CAT. <b>"E" "E"</b>	S.E.	M.E. <b>X</b>
		DAY <b>X</b>		NIGHT

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Walker, B.R.J.	P/O	164773	F.I.	Uninj.	NO.	DATE
Butters, R.	LAC	1584569	P.P.	Uninj.	D 14 (REVISED)	
					NO.	CHECKED
					#23	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
Jacobs L6MB	2673/9985 17691/9064 25904/10608 15885/2070 Nal	46	31	71	79	175	183
		33	27	50	89	79	138

ACCIDENT CLASSIFICATION

COMMAND  
MONTH  
STAGE OF FLIGHT

FORCED LANDING  
TAXIING  
LANDING  
TAKE-OFF  
FLIGHT  
STATRY  
FATAL  
INJ.

3RD  
5  
RAF  
M

PURPOSE OF FLIGHT:

Instrument Flying Exercise.

NATURE OF ACCIDENT:

Pilot states that while taxiing along taxi-strip and attempting to pass between parked a/c and a patch of soft ground he collided with Anson 8454.

TECHNICAL OFFICER'S REPORT:

~~MULT~~  
TCA/PCT  
MA/XA  
TCA/PCT  
MA/XA

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

*Pending*

CLASSIFICATION:

9. Collisions.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN: