

ACCIDENT CLASSIFICATION

UNIT # 5 S.F.T.S.
Brantford, Ont

COM. 1

PLACE M.A.

DATE 12-7-44-1715

H.Q. FILE 1100-75-54

A/C TYPE ANSON II

NO. 7554

CRASH CAT. "D5"

S.E. M.E. DAY NIGHT
X X

PERSONNEL Norbury, R.G.

RANK LAC NUMBER R221173

DUTY PP

INJURIES N11

SIGNAL
NO. A52 DATE 15-7

D 14 (REVISED)

NO. 7 CHECKED

27

ENGINE Jacobs 16MB ENGINE NUMBER (S) 2781/16601
25728/15417


HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE		TOTAL	
		DUAL	SOLO	DUAL	SOLO
33	23	99	76	138	107

ACCIDENT CLASSIFICATION

COMMAND MONTH STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STRATRY
FATAL
INJ.
SRD
S
M
N



PURPOSE OF FLIGHT:

Flapless landings.

NATURE OF ACCIDENT:

Structural failure of tail wheel pylon after flapless landing had been executed.

CLASSIFICATION:

7. Others

SECONDARY OR CONTRIBUTORY FACTORS:

38. Tail wheel.

TECHNICAL OFFICER'S REPORT:

Failure of tail wheel pylon.

LUC/UDM LUC/UTWF

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

ACTION TAKEN:

Nil