


ACCIDENT CLASSIFICATION

UNIT # 6 B.C.S. Mt. View, Ont		COM. 1	PLACE M.A.		DATE 18-7-44	TIME 0230			
A/C TYPE Anson II		NO. 8226	CRASH CAT. "D"		S.E.	M.E. X	DAY NIGHT X		
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL		
Wyght, F.C.L.		P/O	J37030	P	Nil		No. DATE		
Thompson, R.		GB LAC	1697878	OC	Nil		No sig.		
Todd, W.J.		GB LAC	1891273	OC	Nil		D 14 (REVISED)		
							NO. CHECKED		
							2		
							# 37		
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS					
Jacobs L6MB		19720/25832		INST.	NIGHT	ON TYPE		TOTAL	
		26996/10250				DUAL	SOLO	DUAL	SOLO
				73	75	9	138	159	287
								159	46

ACCIDENT CLASSIFICATION

COMMAND
MONTH
STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ.
INJURY 3RD



PURPOSE OF FLIGHT:

Night bombing exercise.

NATURE OF ACCIDENT:

Wheels up landing - obscure.
Quarter moon- slight haze.

TECHNICAL OFFICER'S REPORT:

Stbd U/C operating 1 evers bent after take off,
presumably due to contact with runway after starting
to raise u/c. LUC/PCDUW/UCDO/

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

OUC/PCDUW/UCDO

CLASSIFICATION:

5. U/C failure.

SECONDARY OR CONTRIBUTORY FACTORS:

34. U/C strain.

ACTION TAKEN:

Nil.