



PURPOSE OF FLIGHT:

Armament exercise.

NATURE OF ACCIDENT:

Pilot reports that after 20 minutes flying, stbd engine failed. A return to Carberry and a successful landing were made.

TECHNICAL OFFICER'S REPORT:

Failure of intermediate cam gear.

SFE/ES/VA/D/I

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SFE/ES/VA/D/I

SUMMARY No.

CLASSIFICATION:

18. Misc. technical.

SECONDARY OR CONTRIBUTORY FACTORS:

27. Engine trouble - no damage.

ACTION TAKEN:

NIL