

CASPIR Aircraft Accident Cards

Serial: 2957

Title: North American Harvard Mk.II serial:2957 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1944-July-13. Harvard II s/n 2957. This accident involved 1 person. Barker CR

Keywords: RAFHarvard II,2957,34 SFTS,34 Service Flying Training School,Aerodrome,1944-July-13,BarkerRCAF L20

Created: 1944-07-13

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2957>

PURPOSE OF FLIGHT:

Clear Hood exercises.

NATURE OF ACCIDENT:

Pilot states u/c failed to lock down in spite of use of emergency system. Pilot landed on completion of landing run port leg collapsed.

CLASSIFICATION:

5. U/C failure.

SECONDARY OR CONTRIBUTORY FACTORS:

TECHNICAL OFFICER'S REPORT:

Port u/c pin failed to operate. Considerable amount of grit was present around mechanism and failure of pin to function correctly is attributed to this.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

LUC/UM

ACTION TAKEN:

Nil.