



PURPOSE OF FLIGHT:

W/T training exercises.

NATURE OF ACCIDENT:

Engine throwing oil badly.  
Landed to have windshield wiped,  
returned immediately after.

TECHNICAL OFFICER'S REPORT:

Prop leathers required tightening.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

18. Misc. Technical.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil.