

ACCIDENT CLASSIFICATION

UNIT 7 S.I.F.S. MacLeod, Alta.		COM. 4	PLACE Woodhouse, Alta.		DATE 2-8-44	TIME 0840		
A/C TYPE LISON II		NO. 8247	CRASH CAT. <del>1</del> 5		S.E.	M.E. X	DAY X	NIGHT

PERSONNEL		RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Bradford, J.G.	E/C	J41243	FI	Uninj.	NO.	DATE	
Lyman, M.F.	LAC	R211949	FP	Uninj.	D 14 (REVISED)		
					NO.	CHECKED	
					#13		

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.		ON TYPE		TOTAL	
Jacobs 16MB	4247/17069 Serbauch 10086/26832 Nil	48	42	DUAL	SOLO	DUAL	SOLO
		24	21	67	41	111	85

ACCIDENT CLASSIFICATION

COMMAND

MOBILE

STAGE OF FLIGHT

FORCED LANDING

TAXIING

LANDING

TAKE-OFF

FLIGHT

STRATRY

FATAL


INJ.

3RD

5

RAF

M



PURPOSE OF FLIGHT:

Navigation Cross Country.

TECHNICAL OFFICER'S REPORT:

Port engine failed.

NATURE OF ACCIDENT:

Failure of port engine due to broken crankshaft.

*FB/ET/AM/D/I*

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

17. Forced Landing.

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine trouble - Accident.

ACTION TAKEN:

Nil