

CASPIR Aircraft Accident Cards

Serial: FP880

Title: Anson II serial:FP880 - Crash Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 2 aircraft on 1944-August-07. They are: Anson s/n FP879, Anson II s/n FP880. This accident involved 1 person. Riddell GLF

Keywords: RCAFAnson II,FP880,12 SFTS,12 Service Flying Training School,Aerodrome,1944-August-07,RiddellRCAF L20

Created: 1944-08-07

ACCIDENT CLASSIFICATION

UNIT 12 S.F.T.S. Brandon	COM. 2	PLACE M.A.	DATE 7-8-44	TIME 1325
A/C TYPE ANSON. ANSON II	NO. FP879 880 -8	CRASH CAT. Nil. "D"2	H.Q. FILE 1100-8-80	S.E. M.E. DAY NIGHT
			X	X

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL
RIDDELL, G.L.F.	SGT	R180081	P	Uninj.	No. DATE No sig
					D 14 (REVISED)
					No. CHECKED 1 X
					#18

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
Jacobs L6MB	P9239/17866 Nil S9870/25500 Nil	INST.	NIGHT	ON TYPE		TOTAL	
		DUAL	SOLO	DUAL	SOLO	DUAL	SOLO
		55	36	4	7	161	137


ACCIDENT CLASSIFICATION

COMMAND

MONTH

STAGE OF FLIGHT

- FORCED LANDING
- TAXIING
- LANDING
- TAKE-OFF
- FLIGHT
- STRATY
- FATAL
- INJ.
- INJURY 3rd



PURPOSE OF FLIGHT:

Navigation exercise.

TECHNICAL OFFICER'S REPORT:

MULT
TCA / PCT

NATURE OF ACCIDENT:

Taxiing accident. Port wing of Anson 880 came in contact with propellor hub of Anson 879, which was parked, causing damage to port wing tip of Anson 880.

NIL MA / XA

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

9. Collisions

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Logged and log book endorsed.