

## CASPIR Aircraft Accident Cards

---

**Serial:** 11417

**Title:** Avro Anson Mk. II serial:11417 Accident Card

**Author:** Royal Canadian Air Force (RCAF)

**Subject:** This accident involved 1 aircraft on 1944-August-10. Anson II s/n 11417. This accident involved 2 people. Bailey RE, Whitley GE

**Keywords:** RCAFAnson II,11417,19 SFTS,19 Service Flying Training School,Aerodrome,1944-August-10,Bailey,WhitleyRCAF L20

**Created:** 1944-08-10

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#11417>



PURPOSE OF FLIGHT:

Forced precautionary and single engine landings.

TECHNICAL OFFICER'S REPORT:

Investigation indicates that u/c latches were not clearing u/c cross member but rather bumping up against it.

NATURE OF ACCIDENT:

When u/c selected down port wheel failed to lock, Emergency methods tried but were unsuccessful. When landing made port wheel collapsed.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

LUC / UDL

CLASSIFICATION:

5. U/C failure.

SECONDARY OR CONTRIBUTORY FACTORS:

35. U/C defect.

ACTION TAKEN:

NIL