

ACCIDENT CLASSIFICATION

UNIT 6 B.G.S. Mountain View	COM. 1	PLACE M.A.	DATE 13-8-44	TIME 2245
A/C TYPE ANSON II	NO. 7446	CRASH CAT. "D"	H.Q. FILE 1100-74-46	S.E. M.E. DAY NIGHT
			X	X


PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
MCNEIL, S.B.F.	P/O	J4349	P	Uninj.	NO.	DATE
DRURY, C.E.	LAC	F282379	DC	Uninj.		
FERNWORN, A.	LAC	F281582	CC	Uninj.		
					D 14 (REVISED)	
					NO. 2	CHECKED
					#26	

ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS					
				INST.	NIGHT	ON TYPE		TOTAL	
						DUAL	SOLO	DUAL	SOLO
Jacobs	L6MB	16511/2690	NH1						
		25367/9737	NH1	45	49	8	168	169	300

ACCIDENT CLASSIFICATION

COMMAND  
MONTH  
STAGE OF FLIGHT

FORCED LANDING  
TAXIING  
LANDING  
TAKE-OFF  
FLIGHT  
STRUT  
FATAL  
INJ.  
3RD  
5



PURPOSE OF FLIGHT:

Night bombing exercise.

TECHNICAL OFFICER'S REPORT:

NATURE OF ACCIDENT:

Pilot made take-off, becoming airborne started to climb but failed to clear the trees off end of No. 1 runway causing damage to stbd wing of a/c.

NIL  
OCO/PCL/PSF/ON  
COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

13. Collisions.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL