

ACCIDENT CLASSIFICATION

UNIT	8 B.G.S.	COM.	4	PLACE	M.A.	DATE	21-8-44	TIME	2200
A/C TYPE	ANSON II			NO.	7428	H.Q. FILE	1100-74-28		
		CRASH CAT.	"B"	S.E.		M.E.	X	DAY	
						NIGHT			X


PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
					NO.	DATE
Danley, E.L.	P/O	J42084	P	Uninj.		
Powell, A.J. AUS	LAC	441696	AB	Uninj.	A226	22/8
Phillips, D.G. AUS	LAC	439001	AB	Uninj.	D 14 (REVISED)	
Pederson, A.	LAC	R21641	WAG	Uninj.	NO.	CHECKED
					#39	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				DUAL	SOLO	DUAL	SOLO
Jacobs L6MB	PT16987/3166 SB26700/9954	51	135	16	170	125	389
							125 514

ACCIDENT CLASSIFICATION

COMMAND
 MONTH
 STAGE OF FLIGHT

FORCED LANDING
 TAXIING
 LANDING
 TAKE-OFF
 FLIGHT
 STATRY
 FATAL
 INJ.
 3RD
 S



PURPOSE OF FLIGHT:

Bombing Exercise.

NATURE OF ACCIDENT:

Overshot runway - struck fence and ditch.

TECHNICAL OFFICER'S REPORT:

Nil Technical Officer's report.

LO/PSO

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

1. Overshot.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Log book endorsed. Administrative action. Pilot doing tour of Control Tower duty.