

CASPIR Aircraft Accident Cards

Serial: 13881

Title: Avro Anson VI serial:13881 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-August-23. Anson VI s/n 13881. This accident involved 4 people. Debloeme DR, Edwards RG, Harris AG, Shaw JR

Keywords: RCAFAnson VI,13881,6 BGS,6 Bomb & Gunnery School,Aerodrome,1944-August-23,Debloeme,Edwards,Harris,ShawRCAF L20

Created: 1944-08-23

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#13881>

PURPOSE OF FLIGHT:

Familiarization.

NATURE OF ACCIDENT:

On landing pilot selected u/c "Up" instead of flap lever prior to stopping a/c. Instructor immediately selected u/c "Down" opened the throttles and became airborne. When u/c selected down on down wind leg stbd wheel would not lock in down position.

CLASSIFICATION:

5. U/C failure.

SECONDARY OR CONTRIBUTORY FACTORS:

33. U/C drill - on ground.

TECHNICAL OFFICER'S REPORT:

Stbd u/c actuating and locking mechanism damaged by weight of a/c after the mechanism had been unlocked.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

LUC/PCDUW/UCDL

ACTION TAKEN:

Pilot logged "Gross Carelessness" in accordance with C.A.P. 100 Sec. 4 para 31 (a) sub para (iii).