

TYPE OF A/C		ACCIDENT CLASSIFICATION										DATE 15-8-44		TIME 0920		COMMAND
UNIT 9 B.G.S. Mont Joli		COM. 3		PLACE M.A.		H.Q. FILE 1100-54-12										
A/C TYPE BATTLE		NO. 5412		CRASH CAT. "D"		S.E. X		M.E.		DAY X		NIGHT				
PERSONNEL		RANK	NUMBER	DUTY	INJURIES			SIGNAL								
FANCETT, D.A.		SGT	B200699	P	Uninj.			NO. M100		DATE 15-8						
								D 14 (REVISED)								
								NO. 3		CHECKED ☒						
										#3						
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS								MONTH				
Merlin V		452/5311 slight		INST.		NIGHT		ON TYPE		TOTAL		STAGE OF FLIGHT				
				DUAL		SOLO		DUAL		SOLO		FORCED LANDING				
				30		19		2		97		127				
												TAXYING				
												LANDING				
												TAKE-OFF				
												FLIGHT				
												STAT'RY				
												FATAL				
												INJ.				
												3RD				
												RAF				
												M 2				
ACCIDENT CLASSIFICATION																

PURPOSE OF FLIGHT:

Scheduled target a/c on camera gun exercise.

NATURE OF ACCIDENT:

Wheels up landing on aerodrome due to serious external glycol leak.

TECHNICAL OFFICER'S REPORT:

Glycol escaping from Coolant Header Tank.. Airman who carried out D.1 failed to replace filler cap after checking tank for glycol

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

LB/AOP/ES/GL/G/I/UNT/XFM

CLASSIFICATION:

17. Forced landing.

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine trouble - accident.

ACTION TAKEN:

Airman charged under A.F.A. 39A(1) (a)