

CASPIR ARCHIVAL METADATA

Serial:	10707
Title:	Fairchild Cornell Mk. II serial:10707 Accident Card
Author:	Royal Canadian Air Force (RCAF)
Subject:	This accident involved 1 aircraft on 1944-August-23. Cornell II s/n 10707. This accident involved 2 people. Dillon RM, Higgins D
Keywords:	RCAFCornell II,10707,2 FIS,2 Flying Instructor School,Nobleford Alberta,1944-August-23,Dillon,HigginsRCAF L20
Created:	1944-08-23
Link:	https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000434#10707

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Test Flight after New Stbd. Main Landing Gear Commanding Officer's Report:
had been installed. Engine Failure.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

FB/ROP/ES/NK/NK/I

Had just finished doing a roll off. COMPOSITION:

Was flying straight and level, engine
apparently functioning properly, when it

cut out. Changing over tanks, use of
webble pump, and checking switches, RECOMMENDATIONS:
to make engine catch. Turned off switches
and gas cocks and made forced Landing.

PRIMARY CAUSE:

17. Forced Landing.

26. Engine Trouble - Accident.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____