

ACCIDENT CLASSIFICATION

UNIT	132 Sqdn	COM.	W	PLACE	Tofino, B.C.		DATE	11-8-44	TIME	1530	COMMAND			
	A/C TYPE		HARVARD II		No.	3239	CRASH CAT.	"D"	S.E.	X		M.E.		DAY
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL		MONTH					
CARTER, H.R.		E/O	J3519	P	Uninj.		No.	X257	DATE	11-8	STAGE OF FLIGHT			
							D 14 (REVISED)							
							No.	1	CHECKED	4				
									#21					
ENGINE	ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS											
Wasp	5147/12153		INST.	NIGHT	ON TYPE		TOTAL							
					DUAL	SOLO	DUAL	SOLO						
			40	22	90	152	136	356						

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

A/E test²

TECHNICAL OFFICER'S REPORT:

NIL

~~ANT~~
TM/FCM/UBP/KFM ✓

NATURE OF ACCIDENT:

Was taxiing Harvard 3239 south on the taxi strip running parallel to the hangers. Swerved to left to watch a row of Venturas and then swung around to look up the taxi strip. As pilot came around he saw an airman in front of him, walking out across the taxi strip at about a 45 degrees angle, right in front of him. Pilot applied brakes, whereupon the Harvard stopped and eased up on its nose.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

11. Others.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL