

CASPIR Aircraft Accident Cards

Serial: AJ930

Title: North American Harvard Mk. II serial:AJ930 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1944-August-15. Harvard IIB s/n AJ930. This accident involved 1 person. Brandler A

Keywords: RAFHarvard IIB,AJ930,34 SFTS,34 Service Flying Training School,Maple Creek,1944-August-15,BrandlerRCAF L20

Created: 1944-08-15

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ930>


ACCIDENT CLASSIFICATION

UNIT # 34 S.F.T.S. Med. Bat; Alta.		COM. 4	PLACE Maple Creek.			DATE 15-8-44	TIME 1650		
A/C TYPE HARVARD 11B		No. AJ930	CRASH CAT. F/L	S.E. X	M.E.	DAY X	NIGHT		
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL		
Brandler, A.		Cpl	35354	PP	Nil		No. DATE No Sig.		
							D 14 (REVISED)		
							No. CHECKED 8		
							# 45		
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS					
Wasp S3H1		132/9314 Nil		INST.	NIGHT	ON TYPE		TOTAL	
						DUAL	SOLO	DUAL	SOLO
				25	7	63	37	106	78

COMMAND MONTH STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STAT'RY
FATAL
INJ.
SND
COURT
M.S.

ACCIDENT CLASSIFICATION



PURPOSE OF FLIGHT:

Solo Cross Country.

TECHNICAL OFFICER'S REPORT:

Nil

NATURE OF ACCIDENT:

Pilot of this a/c encountered heavy thunderstorms with visibility less than one mile. He carried out a precautionary landing without damaging the a/c, which was flown back to base.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

17. Forced landing.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil