

ACCIDENT CLASSIFICATION

UNIT 2 W.S. Calgary	COM. 4	PLACE 11 miles E and 1 mile S of Strathmore	DATE 25-8-44	TIME 1750				
A/C TYPE HARVARD IIB		NO. AJ802	CRASH CAT. "C"20	H.Q. FILE 1300-AJ802				
PERSONNEL		RANK	NUMBER	DUTY	INJURIES	SIGNAL		
HEPBURN, J.P.		P/O	J42879	P	Uninj.	NO.	DATE	
HAMLIN, C.		GB LAC	1802845	PP	Uninj.	D 14 (REVISED)		
						NO.	CHECKED	
						#74		
ENGINE	ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS					
P & W	5072/10605 slight		ON TYPE		TOTAL			
			INST.	NIGHT	DUAL	SOLO	DUAL	SOLO
			47	20	28	212	71	333

COMMAND

MONTH

STAGE OF FLIGHT

- 2
- 4
- 7
- 1
- 2
- 7
- 4
- 2
- 1
- FORCED LANDING
- TAXYING
- LANDING
- TAKE-OFF
- FLIGHT
- STATRY
- FATAL
- INJ.
- 3RD
- INJURY
- 5
- 4

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

W/T exercise.

NATURE OF ACCIDENT:

Black oil covered wind screen
preceded by black smoke from
engine cowling. Pilot took fire
precautions and made wheels up
landing in field.

TECHNICAL OFFICER'S REPORT:

Ruptured gasket in C.S. unit.

FB/AOP/ES/PR/D/I/UCR/B/AE ✓

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

18. Misc. technical.

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine trouble - accident.

ACTION TAKEN:

NIL